

CONTRACT ID: PROJECT: CONTRACT: AWARD AMOUNT: PROJECTED AMOUNT: ADJ. PROJECTED AMOUNT:	646243001 SUP - 646243001 12232501 \$27,006.00 \$27,006.00 \$94,506.00		HIGHWAY: DISTRICT NAME: COUNTY: AREA ENGINEER: AREA NUMBER:	US0082 CHILDRESS DICKENS Matthew Herbstritt P.E. 053	
CONTRACTOR:	WORKQUEST				
ESTIMATE NUMBER: ESTIMATE PAID: ESTIMATE PERIOD: ESTIMATE TYPE: % COMPLETE: % TIME USED: % RETAINAGE:	0007 07/01/2024 to 07/31/2024 PROG 40.43 55.89 0.00		LETTING DATE: AWARD DATE: NOTICE TO PROCEEI WORK BEGIN DATE: ACCEPTED DATE: PHYSICAL WORK CO		12/31/2023 01/02/2024 01/10/2024 01/04/2024 00/00/0000 00/00/0000
RECAPITULATION					
	TOTAL TO DATE	PREV TO DATE	THIS ESTIMATE		
ITEM EARNINGS	\$38,206.00	\$27,006.00	\$11,200.00		
PARTICIPATING	\$0.00	\$0.00	\$0.00		
NON-PARTICIPATING	\$38,206.00	\$27,006.00	\$11,200.00		
RETAINAGE	\$0.00	\$0.00	\$0.00		
LIQUIDATED DAMAGES	\$0.00	\$0.00	\$0.00		
INCENTIVE	\$0.00	\$0.00	\$0.00		
DISINCENTIVE	\$0.00	\$0.00	\$0.00		
OTHER ADJUSTMENTS	\$0.00	\$0.00	\$0.00		
				7	

PAID TO CONTRACTOR

\$38,206.00

\$27,006.00 \$11,200.00

CONTRACT ADJUSTMENTS THIS ESTIMATE

ADJUSTMENT DESCRIPTION: ADJUSTMENT AMOUNT: REMARKS:

There are no Contract Adjustments for this estimate

CERTIFIED AS CORRECT AND ONE COPY HAS BEEN GIVEN TO THE CONTRACTOR

AREA/PROJECT ENGINEER

LINE ITEM ADJUSTMENTS THIS ESTIMATE

ADJUSTMENT DESCRIPTION: ADJUSTMENT AMOUNT: REMARKS:

There are no Line Item Adjustments for this estimate

DATE

PERIOD SUMMARY

CONTRACT TIME STATEMENT

WORK BEGIN DATE:	01/04/2024	ASSESSED LIQ DAMAGES:	0	
TIME CHARGES BEGIN:	01/01/2024	LIQ DAMAGE RATE:	\$618.00	
BID DAYS:	365	LIQUIDATED DAMAGES:	0	
C. O. ADJUSTED DAYS:	0		DAYS AT	
CURRENT DAYS:	365		PER DAY	\$618.00
DAYS CHARGED TO DATE:	204	TOTAL:	\$0.00	
PHYSICAL WORK COMPLETE:	00/00/0000			

DAILY BREAKDOWN

Date or	Days	Days	Diary	Date or	Days	Days
Days	Charged	Credited	Adjustment	Days	Charged	Credited
07/01/2024	1			31	31	0
07/02/2024	1					
07/03/2024	1					
07/04/2024	1					
07/05/2024	1					
07/06/2024	1					
07/07/2024	1					
07/08/2024	1					
07/09/2024	1					
07/10/2024	1					
07/11/2024	1					
07/12/2024	1					
07/13/2024	1					
07/14/2024	1					
07/15/2024	1					
07/16/2024	1					
07/17/2024	1					
07/18/2024	1					
07/19/2024	1					
07/20/2024	1					
07/21/2024	1					
07/22/2024	1					
07/23/2024	1					
07/24/2024	1					
07/25/2024	1					
07/26/2024	1					
07/27/2024	1					
07/28/2024	1					
07/29/2024	1					
07/30/2024	1					
07/31/2024	1					

CONTRACT ID	646243001	ESTIMATE	0007

07 CONTRACTOR'S ESTIMATE PACKAGE

WORK PERFORMED THIS PERIOD

	PROJECT	SUP - 646243001	CONTROL	646243001					
	CATEGORY	001	DESCRIPTION	ROADWAY					
LINE NBR	ITEM SP CODE NBR	DESCRIPTION		UNIT	UNIT PRICE	QTY THIS ESTIMATE	AMOUNT PAID THIS ESTIMATE	Total Bid Quantity	QTY Paid To Date
0100	07526008	TREE REMOVAL (24"	- 30" DIA)	EA	2,500.000	1.000	\$2,500.00	1.00	1.00
	SUPP DESCR	Ttree located approx.	.39 miles W of the US 70/F	TM 654 inter.					
0110	07526008	TREE REMOVAL (24"	- 30" DIA)	EA	1,200.000	1.000	\$1,200.00	1.00	1.00
	SUPP DESCR	Tree located approx	44 miles W of US 70/FM 6	54 inter.					
0120	07526010	TREE REMOVAL (36"	- 42" DIA)	EA	2,500.000	1.000	\$2,500.00	1.00	1.00
	SUPP DESCR	Tree located approx. 1	1.84 miles W of CR 373, R	M 424					
0185	07526008	TREE REMOVAL (24"	- 30" DIA)	EA	5,000.000	1.000	\$5,000.00	1.00	1.00
	SUPP DESCR	Tree located in the Mu	inday maintenance yard						

TOTAL ITEM EARNINGS THIS ESTIMATE

\$11,200.00

0007

CONTRACT LINE ITEMS

PROJE	CT SUI	P - 64624	3001 CONTROL	646243001					
CATEG	ORY 001		DESCRIPTION	ROADWAY					
LINE NBR	ITEM CODE	SP NBR	DESCRIPTION SUPP DESCRIPTION	UNIT	UNIT PRICE	BID QUANTITY	NET CO QUANTITY	QTY PAID TO DATE	AMOUNT \$
0060	07526005	000	TREE REMOVAL (4" - 12" DIA)	EA	5,000.000	3.000	0.000	3.00	15,000.00
0065	07526006	000	TREE REMOVAL (12" - 18" DIA)	EA	5,200.000	1.000	0.000	1.00	5,200.00
0070	07526017	000	STUMP REMOVAL (12" OR LESS)	EA	4,802.000	1.000	0.000	1.00	4,802.00
0075	07526024	000	TREE TRIMMING (0"-12")	EA	2,004.000	1.000	0.000	1.00	2,004.00
0100	07526008		TREE REMOVAL (24" - 30" DIA)	EA	2,500.000	0.000	1.000	1.00	2,500.00
			Ttree located approx39 miles	W of the US 70/FM 654 inter.					
0110	07526008		TREE REMOVAL (24" - 30" DIA)	EA	1,200.000	0.000	1.000	1.00	1,200.00
			Tree located approx44 miles						
0120	07526010		TREE REMOVAL (36" - 42" DIA)	EA	2,500.000	0.000	1.000	1.00	2,500.00
			Tree located approx. 1.84 miles						
0185	07526008		TREE REMOVAL (24" - 30" DIA)	EA	5,000.000	0.000	1.000	1.00	5,000.00
			Tree located in the Munday ma	intenance yard					
							Category	Subtotal	\$38,206.00
PROJE	CT SUP	- 646243	001 CONTROL	646243001					
CATEG	ORY 001		DESCRIPTION	ROADWAY					
					UNIT	BID	NET CO	QTY PAID	AMOUNT
LINE	ITEM	SP	DESCRIPTION	UNIT					
NBR	ITEM CODE	SP NBR	DESCRIPTION SUPP DESCRIPTION	UNIT	PRICE	QUANTITY	QUANTITY	TO DATE	(\$)
				UNIT					
NBR	CODE		SUPP DESCRIPTION	EA	PRICE	QUANTITY	QUANTITY	TO DATE	(\$)
NBR	CODE		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA)	EA	PRICE	QUANTITY	QUANTITY	TO DATE	(\$)
NBR 0105	CODE 07526008		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W o	EA f the US 70/FM 654 inter. EA	PRICE 4,500.000	QUANTITY 0.000	QUANTITY 1.000	TO DATE 0.000	(\$) 0.00
NBR 0105	CODE 07526008		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W o TREE REMOVAL (24" - 30" DIA)	EA f the US 70/FM 654 inter. EA	PRICE 4,500.000	QUANTITY 0.000	QUANTITY 1.000	TO DATE 0.000	(\$) 0.00
NBR 0105 0115 0125	CODE 07526008 07526008 07526011		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W of TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass	PRICE 4,500.000 4,000.000	QUANTITY 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000	(\$) 0.00 0.00 0.00
NBR 0105 0115	CODE 07526008 07526008		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W of TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA)	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA	PRICE 4,500.000 4,000.000	QUANTITY 0.000 0.000	QUANTITY 1.000 1.000	TO DATE 0.000 0.000	(\$) 0.00 0.00
NBR 0105 0115 0125 0130	CODE 07526008 07526008 07526011 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W o TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass	PRICE 4,500.000 4,000.000 4,500.000 2,000.000	QUANTITY 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000	(\$) 0.00 0.00 0.00 0.00
NBR 0105 0115 0125	CODE 07526008 07526008 07526011		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W of TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA)	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA	PRICE 4,500.000 4,000.000 4,500.000	QUANTITY 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000	(\$) 0.00 0.00 0.00
NBR 0105 0115 0125 0130 0135	CODE 07526008 07526008 07526011 07526009 07526011		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W of TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of Sh	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1 6 - N side of the road	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000	QUANTITY 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000	(\$) 0.00 0.00 0.00 0.00 0.00
NBR 0105 0115 0125 0130	CODE 07526008 07526008 07526011 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W or TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA)	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1 6 - N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000	QUANTITY 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000	(\$) 0.00 0.00 0.00 0.00
NBR 0105 0115 0125 0130 0135 0140	CODE 07526008 07526001 07526009 07526011 07526008		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W or TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA) Tree located approx. 4562' E of FM	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1 6 - N side of the road EA 1043, N side of the road	PRICE 4,500.000 4,000.000 4,500.000 4,500.000 6,000.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000	(\$) 0.00 0.00 0.00 0.00 0.00
NBR 0105 0115 0125 0130 0135	CODE 07526008 07526008 07526011 07526009 07526011		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx40 miles W or TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA)	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA 1 6 - N side of the road EA 1043, N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000	QUANTITY 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000	(\$) 0.00 0.00 0.00 0.00 0.00
NBR 0105 0115 0125 0130 0135 0140 0145	CODE 07526008 07526011 07526009 07526011 07526008 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W o TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1 6 - N side of the road EA 1043, N side of the road EA 1043 - N side of the road	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000 6,000.000 6,000.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000 0.000	 (\$) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00
NBR 0105 0115 0125 0130 0135 0140	CODE 07526008 07526001 07526009 07526011 07526008		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W o TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA d 6 - N side of the road EA 1043, N side of the road EA 1043 - N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 4,500.000 6,000.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000	(\$) 0.00 0.00 0.00 0.00 0.00
NBR 0105 0115 0125 0130 0135 0140 0145	CODE 07526008 07526011 07526009 07526011 07526008 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W o TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA d 6 - N side of the road EA 1043, N side of the road EA 1043 - N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000 6,000.000 6,000.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000 0.000	 (\$) 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00
NBR 0105 0115 0125 0130 0135 0140 0145 0150	CODE 07526008 07526011 07526009 07526001 07526008 07526009 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W o TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 5939' E of FM	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1043, N side of the road EA 1043 - N side of the road EA 1043, N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000 6,000.000 6,000.000 2,500.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	 (\$) 0.00
NBR 0105 0115 0125 0130 0135 0140 0145 0150	CODE 07526008 07526011 07526009 07526001 07526008 07526009 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W o TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 30" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 5939' E of FM TREE REMOVAL (30" - 36" DIA)	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1043, N side of the road EA 1043 - N side of the road EA 1043, N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000 6,000.000 6,000.000 2,500.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	 (\$) 0.00
NBR 0105 0115 0125 0130 0135 0140 0145 0150 0155	CODE 07526008 07526011 07526009 07526008 07526009 07526009 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W o TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (42" - 48" DIA) Tree located approx. 9.36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 5939' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 6675' E of FM	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1043, N side of the road EA 1043 - N side of the road EA 1043, N side of the road EA 1043, N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000 6,000.000 6,000.000 2,500.000 3,000.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	 (\$) 0.00
NBR 0105 0115 0125 0130 0135 0140 0145 0150 0155	CODE 07526008 07526011 07526009 07526008 07526009 07526009 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W of TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 48" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 5939' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 6675' E of FM TREE REMOVAL (36" - 42" DIA)	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1043, N side of the road EA 1043 - N side of the road EA 1043, N side of the road EA 1043, N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000 6,000.000 6,000.000 2,500.000 3,000.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	 (\$) 0.00
NBR 0105 0115 0125 0130 0135 0140 0145 0150 0155 0160	CODE 07526008 07526011 07526009 07526011 07526009 07526009 07526009 07526009		SUPP DESCRIPTION TREE REMOVAL (24" - 30" DIA) Tree located approx. 40 miles W of TREE REMOVAL (24" - 30" DIA) Tree located approx. 600' W of CR TREE REMOVAL (42" - 48" DIA) Tree located approx. 8.85 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 9.33 miles W TREE REMOVAL (30" - 36" DIA) Tree located approx. 2783' W of SH TREE REMOVAL (24" - 48" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 4562' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 5939' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 5939' E of FM TREE REMOVAL (30" - 36" DIA) Tree located approx. 6675' E of FM TREE REMOVAL (36" - 42" DIA) Tree located approx. 5954' E of CR	EA f the US 70/FM 654 inter. EA 371 - South side of road EA of the US 83/82 overpass EA of the US 83/82 overpass EA 1 6 - N side of the road EA 1 043 - N side of the road EA 1 043, N side of the road EA 1 043, N side of the road EA 1 043, N side of the road EA	PRICE 4,500.000 4,000.000 4,500.000 2,000.000 4,500.000 6,000.000 6,000.000 2,500.000 3,000.000	QUANTITY 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	QUANTITY 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000	TO DATE 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000	 (\$) 0.00

CONTR	RACT ID	646243001	ESTIMATE	0007	CONTRACTOR'S EST	IMATE PACKAGE			Pag	e 5 of 6
			Tree located approx.	2534' W of FM	267, S side of road					
0175	07526008	;	TREE REMOVAL (24" - 3	30" DIA)	EA	3,500.000	0.000	1.000	0.000	0.00
			Tree located at the N	lunday mainten	ance yard					
0180	07526008		TREE REMOVAL (24" - 3	30" DIA)	EA	5,000.000	0.000	1.000	0.000	0.00
			Tree located at the N	lunday mainten	ance yard					
1005	96026001		PAYMENT ADJUSTMEN	IT-POS	DOL	1.000	1,000.000	0.000	0.000	0.00
1010	96026002		PAYMENT ADJUSTMEN	IT-NEG	DOL	-1.000	1,000.000	0.000	0.000	0.00
								Category Subto	otal	0.00

Category Subtotal

TOTAL ITEM EARNINGS THIS CONTRACT

\$38,206.00

CONSTRUCTION ESTIMATE COMBINED

ITEM CODE	SP NBR	DESCRIPTION	UNIT	UNIT PRICE	BID QUANTITY	QTY PAID TO DATE	AMOUNT (\$)
07526005	000	TREE REMOVAL (4" - 12" DIA)	EA	5,000.000	3.00	3.000	15,000.00
07526006	000	TREE REMOVAL (12" - 18" DIA)	EA	5,200.000	1.00	1.000	5,200.00
07526008		TREE REMOVAL (24" - 30" DIA)	EA	1,200.000	0.00	1.000	1,200.00
		Tree located approx44 miles W of US 70/FM 654 inter.					
07526008		TREE REMOVAL (24" - 30" DIA)	EA	2,500.000	0.00	1.000	2,500.00
		Ttree located approx39 miles W of the US 70/FM 654 inter-					
07526008		TREE REMOVAL (24" - 30" DIA)	EA	5,000.000	0.00	1.000	5,000.00
		Tree located in the Munday maintenance yard					
07526010		TREE REMOVAL (36" - 42" DIA)	EA	2,500.000	0.00	1.000	2,500.00
		Tree located approx. 1.84 miles W of CR 373, RM 424					
07526017	000	STUMP REMOVAL (12" OR LESS)	EA	4,802.000	1.00	1.000	4,802.00
07526024	000	TREE TRIMMING (0"-12")	EA	2,004.000	1.00	1.000	2,004.00

TOTAL ITEM EARNINGS TO DATE

\$38,206.00